

## **AMENDMENTS TO THE FIGURES**

The following corrections to the drawings have been made. Red-lined versions of the drawings and replacement pages are included herewith. Applicant respectfully requests acceptance of the amended drawings.

**Figure 5** – The address “F000-F00F” for COM R (element 512) has been corrected to read “F000:F007”.


**Figure 8** – The missing element numbers 844 and 852 have been added. Element 848 has been corrected to read “MSR IN”, rather than “DEBUG IN”.

**Figure 9** – The missing element number 916 has been added.

**Figure 11** – Element 1120 has been corrected to read “REPORT ERROR”, rather than “RECORD ERROR”.

**Figure 13C** – The designation for element 1356 has been corrected to be “+++”, rather than “+++ATH”.

**Figure 15C** – The element designated as “RR/GRR” has been corrected to have element number 1568, rather than 1588.




MEMORY MAP

**FIG. 5**




FIG. 8







8/16

FIG. 9






10/16




**FIG. 11**




12/16



**FIG. 13A**



**FIG. 13B**



**FIG. 13C**

1350




FIG. 15c